



Introduction of CanSat



GPS

Xbee




Battery

wheels

Motor

Circuit

Result



The connector to a parachute were broken

The CanSat fell freely, and CanSat was broken.





Finally...

Select the motor and battery

- We selected a heavy motor and battery
 - → Necessity to lighten
 - → Strength becomes weak

Schedule management

- Development got behind
 - → lack of development time and test